
Post-earthquake Seismic Retrofit Programs for Improved Reconstruction

by M. Lisbeth Blaisdell, S.E.¹

¹Director of Engineering, Build Change, lizzie@buildchange.org, 900 Bay Drive #1022, Miami Beach, FL 33141



NC - Second floor walls not aligned

C – Provided free-standing column is compliant, see Item 6.1

C - There are perpendicular walls that extend at least 60cm

on each side of the wall above

C - There are parallel walls with at least ¼ length

upper wall overlapping with the lower wall

level (2/3 Maximum Considered Earthquake)

(low ductility)